

## SinuTrain DEMO machine



Version : V4.95 HF1 (oder later version)

Machine : DEMO-Milling machine















## Subroutine Programs

### Cutting sequence overview



## Programs list

Program	3D view of simulation	Clamping situation	
SP01_WW1.MPF  (out contour cutting at the base of the part)			
SP01_WW2.MPF  (Handle pocket cutting and chamfering)			
SP01_WW3.MPF  (Handle pocket chamfering on backside)			

<p>SP02_WW1.MPF</p> <p>(Facing, chamfering, pocket, slot cutting, drilling, and tapping on top face)</p>			
<p>SP02_WW2.MPF</p> <p>(Facing, chamfering, pocket, slot cutting, drilling, and tapping on right face)</p>			
<p>SP02_WW3.MPF</p> <p>(Facing, chamfering, pocket, slot cutting, drilling, and tapping on 45-degree face)</p>	